Approved For Release 2006/01/30 : CIA-RDP69B00404R000100470006-8

FORM 12-67 2820

(44)

CLASSIFIED MESSAGE

FILE INFO

SECRET
(When Filled In)

PRIORITY

16 MAY 68 65608

REPRODUCTION PROHIBITED

ACTION																			
	1	OXC		6				11	RB	16 MAY 68		16							
	2	11		7				12				17							
	3	OAPS		8				13				18							
	4	COMMO	"	9				14				19							
	5			10				15		ROUTINE		20							

CHIEF	INTERACT INFO
OPS	
PLANS	
HOLD FOR:	
C.I.	

25X1 S E C R E T 16 1355Z MAY 68 CITE [redacted]

PRIORITY [redacted]

OXCART OPS

25X1 REF: [redacted]

1. DUE TO POOR PROPOGATION, INTERFERENCE, AND OTHER SIMILAR PROBLEMS, B.W. READOUTS ARE NOT 100 PERCENT RELIABLE. TO NOTIFY THE PILOT BY VOICE CODE TO REPEAT EWS BIT MAY VERY WELL NOT CORRECT THE PROBLEM AND/OR CONFUSE PILOT INTO SUSPECTING EWS PROBLEMS. ADDITIONALLY, WE BELIEVE IT BEST TO MAINTAIN VOICE SILENCE ON HF DISCRETE FREQUENCIES.

2. WE BELIEVE THE BEST SOLUTION TO THE PROBLEM IS IN THE COCKPIT. WE HAVE BRIEFED ALL PILOTS TO CLOSELY OBSERVE EWS LIGHTS DURING BIT AND IF TEST IS NOT COMPLETELY SUCCESSFUL TO REPEAT BIT'S AS TIME PERMITS TO OBTAIN SUCCESSFUL BIT PRIOR TO REACHING MANDATORY ABORT POINT. POST FLIGHT ANALYSIS WILL REVEAL WHETHER APPARENT EWS MALFUNCTION IS DUE TO PROPOGATION, BW, BIT OR OTHER PROBLEMS.

S E C R E T

BT

25X1

25X1

25X1

BX6858 charge up file 20-22

Return to OXC

Ple prepare msg for [redacted] signature to release

Approved For Release 2006/01/30 : CIA-RDP69B00404R000100470006-8